



Contribution ID: 42

Type: Poster

Structural damage evaluation of a ceramic matrix composite

Friday, 27 November 2015 13:30 (45 minutes)

We studied Ceramic Matrix Composites (CMC) as a new class of structural materials that combine high strength at high temperatures with moderate toughness. Mapping the failure of CMC under mechanical load explains the mechanisms responsible for their toughness. In this study, the correlation of the x-ray radiographs of CMC samples to critical points in the load/displacement curve show that the fibre bundles slowed crack propagation due to strain energy being expended in breaking these fibres and in pulling bundles out of the surrounding matrix material. The results were also complemented with micro X-ray Computed Tomography after failure. Finally, mapping the strain evolution at length scales of micrometres during bending were done using Digital Image Correlation.

Keywords

composite, tomography, X-rays, mechanical test

Primary author: Dr ARHATARI, Benedicta (La Trobe University)

Co-authors: Dr ABBEY, Brian (La Trobe University); Dr THORNTON, John (Defence Science and Technology Organisation); Mr ZONNEVELDT, Matthew (Defence Science and Technology Organisation)

Presenter: Dr ARHATARI, Benedicta (La Trobe University)

Session Classification: Poster Session 2

Track Classification: Advanced Materials